

81-158PB Replacement Pulse Board Park Problem

Application: CARDONE Wiper Motor Pulse Board part number 81-158PB. See catalog for

proper vehicle applications.

Problem: Wipers will not park after replacing Pulse Board.

Cause: Contact arms on Pulse Board may not be contacting Wiper Motor. Packing material or movement during shipping may have bent contacts.

Check position of contact arms before installation. Contacts should be approximately 1 inch (25 mm) above circuit board (see picture). Correct contact position ensures proper Wiper Motor parking function.

Note: Refer to PROTECH PT 40-0003 and PT 40-0004 for additional troubleshooting tests for Wiper Motors and Pulse Boards.


For other ProTech publications, visit www.cardone.com

CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799

SCA3211 PT 40-0005

Window Lift Motors Re-engineered to perform better than new

CARDONE's Motors coverage includes:



- Window Lift Gear Kits
- Window Lift Motors
- Wiper Motors

O.E. Gaskets - CARDONE, through extensive engineering research, has found that O.E. gaskets are often weak and are the cause of motor failure. CARDONE remanufactures all of its Window Lift Motors with a top quality gasket as a replacement for the O.E. gasket. The strength of the gasket ensures the unit will be protected in all situations. This saves the customer time and money from unnecessary repairs.



- 12-month / 18,000 mile warranty
- Contact your local auto parts store or visit our web site, www.cardone.com, for more information on this and other CARDONE products today!



