
## TECHNICAL TIP

536-2TB pg 1 of 3

# This chart is provided to aid you in diagnosing problem areas of the charging system.


Faulty wiring to the voltage regulator is a frequent cause of charging system complaints.

THE VEHICLE HARNESS CONNECTOR IS SHOWN, FACING THE CONTACTS.



# TECHNICALTIP

### 536-2TB pg 2 of 3



## TECHNICALTIP

**536-2TB** pg 3 of 3

#### These units are interchangeable

Although the unit you purchased may not look exactly like the one removed from the vehicle, it will install and operate with no modifications necessary.

