

Please Review

1995-1998 FORD CONTOUR 1995-1998 MERCURY MYSTIQUE 2.0L and 2.5L

Ford Motor Co. Warning

The charging system indicator may be on or the battery may be dead. This situation may be due to a poor electrical connection on the Alternator output wire. Inspect or replace as follows.

The alternator B+ cable runs from the B+ stud at the alternator to a 175 Amp “mega fuse” then to the starter solenoid. This is the cable that will need to be replaced if your car is experiencing this problem. Ford Motor Co. part number is F5RZ-14300-FA. If the alternator B+ stud is damaged, you must also replace the alternator.

