

## Don't Let the Power Steering Snake Bite You

**Application** All vehicles equipped with power steering.

Problem Power steering component failure (i.e., Rack & Pinion, Gear Box,

Pump, Control Valve or Power Cylinder).

Cause Contamination in the steering system.

During installation of the replacement unit carefully inspect the hydraulic hoses. Hoses that appear harmless may have hidden problems. They deteriorate from the inside out, passing contamination throughout the entire system. This results in premature failure of the steering system. ALWAYS FLUSH THE ENTIRE SYSTEM AND INSPECT/REPAIR HOSES TO PREVENT WARRANTY PROBLEMS.



FAILURE TO INSPECT/REPAIR HOSES COULD COME BACK TO BITE YOU!

©2020 CARDONE Industries, Inc. ProTech® is a registered trademark owned by CARDONE Industries, Inc. CARDONE™ is a pending trademark registration owned by CARDONE Industries, Inc.

JEB4200 PT 20-0005