

CARDONE ProTech

Supporting Today's Professional Technician



In-Line Power Steering Filter — An Ounce of Prevention

Application:

All power steering equipped vehicles.

Problem:

Premature failure of power steering components.

Cause:

Particles not removed during the flushing process or particles from everyday wear of components and hoses cause valves to stick and block fluid flow.

Solution:

When replacing any power steering component, always flush the entire system and then install an in-line filter such shown below (part 20-0038F). Be sure to use OE recommended or equivalent fluid, see Pro Tech 20-0027 for more information.



In-Line Filter 20-0038F

Note:

This ProTech bulletin is supplied as technical information only and is not an authorization for repair.

For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799