



# TECHNICAL SERVICE BULLETIN

## COOLING SYSTEM

### DODGE/CHRYSLER HEATER HOSE "Y" CONNECTOR PRONE TO CRACKING

Due to a high replacement demand, Gates Engineers have developed a solution for the two heater hose assembly "Y" connectors that are prone to cracking. The "Y" assembly has been developed from a more robust 35% glass fill to ensure a stronger more reliable component.

The solution does not end with the more robust assembly, as both heater hoses are available individually without the rear steel heater tubes. This allows for time saving maintenance or repairs to be performed due to the difficulty associated with installation of the steel tube placement.



PART # 23931

PART # 23933



OE HOSE ASSEMBLY

**NOTE:** The OE dealer only offers the entire assembly, including the rear heater pipe. The heater pipe does not fail and including this in the assembly creates a more difficult repair.

BULLETIN TSB\_038\_US

#### PART NUMBER:

- 23931
- 23933

#### MAKE:

- Chrysler
- Dodge

#### MODEL:

- Town & Country
- Grand Caravan

#### YEAR:

- 2008-2009

#### ENGINE:

- 3.3L
- 3.8L
- 4.0L

FOLLOW @GATESAUTO

