

PROBLEM

Solver™ BULLETIN

www.moogproblemsolver.com


Difficulty Sourcing All Axle Service Repair Parts

Various GM, Ford,
and Dodge Trucks

PROBLEM:

Difficulty in finding parts necessary for complete repair on 60 Series axles

- Difficulty for technicians and fleet repair facilities in finding sources for all of the parts necessary to do a complete repair on 60 Series axles.
- There are no provisions on the existing axle to allow camber angle changes.




Description	Application	Replacement Part No.
4WD 60 Series Axle Service Kit	Chevrolet/GMC K30, V30, K3500 and V3500 1977-91	K6652
	Dodge Truck W200 and W250 1957-93. W300 and W350 1961-93	K992
	Ford F250 1972-79.	K8832
	F350 1979 and 1985-91	K8833
	Ford Trucks 1985-91	K8833

SOLUTION:

MOOG® K6652, K992, K8832, K8833

- MOOG's K6652, K8832 and K8833 provide upper and lower repair kits for 4WD 60 series axles, making MOOG the only complete repair solution in the aftermarket.
- The K992, eccentric camber-adjusting king pin provides camber alignment adjustments of $-1\frac{1}{2}^{\circ}$ to $+1\frac{1}{2}^{\circ}$. The kit is easily adjustable for the life of the vehicle.



THE PROBLEM SOLVER™

